

[Return to command index](#)

hide traces

command: HIDE <trc-list>

Removes traces from display but keeps them in memory. Hidden traces can be redisplayed with the [DISPLAY](#) command.

parameters

- trc-list> *parameter type: trace list*
List of traces to be hidden.

example

```
hide ALL  
clears display, keeps traces in memory
```

```
hide 1, 4  
remove two specified traces from display
```