

[Return to command index](#)

delete traces

command: DEL <trc-list>

Removes traces from memory (and from display). If these traces are not stored on a q-file, all information about these traces is lost.

parameters

- <trc-list> *parameter type: trace list*
List of traces to be deleted.

example

```
del 1-3  
    delete first three traces of display
```

```
del *  
    delete traces selected by graphic cursor exit with "E"-key
```